## MOZ3004 Wayne

# STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940

### LARGE MINING OPERATIONS 2008 PROGRESS REPORT January 1, 2008 to December 31, 2008

1. Mine Permit Number: \_\_\_\_\_\_ M/023/004

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

2.	Mine Name:	Cement 1	Plant	<u> </u>	Hank	Allen	auarny
3.	Name of Operate	or/Permittee:	Ash Grov Leaming mpany repr	ve Cement Conton, UT 84638 esentative or phone	npany, Bruc -0069 Pho	e Newell, Pone: 435-85	OBox 38069 7-1203
4.	Mine Location: (SW ¼, of NW ¼, of T14S, R3W, S33)						
5.	Report the gross amount of ore mined and waste moved, as well as the arrangement, positioning, or distribution of the material:						
	New Disturd Area Reclain Total Disturt Total life of Was the ore	rial Moved bance med bed Area mine disturbance shipped off s	00 027.6 the to the entite? If no		yd3 2007 2007 2007 ore located?		hipped
6.	Briefly describe the reclamation work performed during the past year. A map showing reclaimed areas and dates is suggested. (Submit form MR-SITE for an application for full or partial bond/site release). NO RECLAMATION in 2007						
7.	Include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.						
correct to t	Name (Typed of Title of Operator Signature of Op	r Print): Bruer: Plant Manerator: 23 A	l belief. ce Newel ager معمد نا	1 Henell	RI	ECEIVE	 D
O:\FORMS\reports\MR-AR-LMO2008.doc  JAN 1 2 2009						109	

#### STATE OF UTAH

#### DEPARTMENT OF NATURAL RESOURCES

#### DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940

#### LARGE MINING OPERATIONS 2008 PROGRESS REPORT January 1, 2008 to December 31, 2008

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

1.	Mine Permit Number:	M/023/004				
2.	Mine Name: Hank A	Allen Quarry				
3.		: Ash Grove Cement Company, Bruce Newell, POBox 38069  Leamington, UT 84638-0069 Phone: 435-857-1203  company representative or phone number have changed, please provide a ce of Intention.				
4.	Mine Location: <u>T15S, R3W.</u>	, S4 and S5; T14S, R3W, S32 and S33				
5.	Report the gross amount of ore mined and waste moved, as well as the arrangement, positioning, or distribution of the material:					
	New Disturbance Area Reclaimed Total Disturbed Area *Total life of mine disturban Was the ore shipped off	1,074,589 Tons, oryd3 186,236 Tons, oryd3 0				
W	here is the waste located? T15	S, R3W, S4 and S5				
6.	Briefly describe the reclama reclaimed areas and dates full or partial bond/site rel	tion work performed during the past year. A map showing is suggested. (Submit form MR-SITE for an application for ease).				
7.	Include an updated map d during the year, prepared in	epicting surface disturbance and reclamation performed n accordance with Rule R647-4-105.				
	reby certify, under penalties the best of my knowledge an Name (Typed or Print): Br Title of Operator: Plant Ma Signature of Operator: Date: Date:	nager Suce W Herell				
ob		RECEIVED				
	ports\MR-AR-LMO2008.doc	JAN 1 2 2009				